

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 7220Y**LAD2109-004***Not Authored**Resony B4991**7452.90*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

07 SEP 2021**SMP7220Y**

MR053REH604598923

TOYOTA

COROLLA ALTIS

5.9.2021

LONPAC

11/10/2019

PART**LIST**

- 1 COVER, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 SUPPORT, FRONT BUMPER SIDE, RH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT, FRONT BUMPER
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 GRILLE, RADIATOR, LOWER NO. 1
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 EMBLEM, RADIATOR GRILLE
- 1 COVER, RADIATOR
- 1 COVER, ENGINE UNDER, CENTER
- 1 HOOD SUB-ASSY
- 1 LOCK ASSY, HOOD
- 1 INSULATOR, HOOD
- 1 HINGE ASSY, HOOD, RH
- 1 HINGE ASSY, HOOD, LH
- 1 HEADLAMP ASSY, RH
- 1 HEADLAMP ASSY, LH
- 1 BRACE, HOOD LOCK SUPPORT
- 1 SUPPORT SUB-ASSY, RADIATOR, RH
- 1 SUPPORT SUB-ASSY, RADIATOR, LH
- 1 SUPPORT SUB-ASSY, RADIATOR, UPPER
- 1 DEFLECTOR, RADIATOR SIDE, RH
- 1 JAR ASSY, WINDSHIELD WASHER
- 1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER
- 1 INLET, AIR CLEANER, NO. 1
- 1 RESONATOR, INTAKE AIR

- \$ *B11 CM* 531.10 ✓
- \$ *D11* 68.20 ✓
- \$ *D11* 68.20 ✓
- \$ *Sm* 111.80 ✗
- \$ *R* 399.50 ✗
- \$ *mg* 209.40 ✗
- \$ *mi* 169.60 ✓
- \$ *CM* 712.10 ✓
- \$ *mi* 47.90 ✓
- \$ *D11* 80.70 ✓
- \$ *Sm* 179.40 ✗
- \$ *R* 1,248.80 ✓
- \$ *D11* 135.00 ✓
- \$ *Sm* 280.10 ✗
- \$ *R* 58.90 ✗
- \$ *R* 58.90 ✗
- \$ *CM* 2,487.80 ✓
- \$ *mg R* 2,487.80 ✓
- \$ *R* 164.90 ✗
- \$ *R* 211.00 ✗
- \$ *R* 211.00 ✗
- \$ *R* 277.30 ✗
- \$ *Sm* 80.70 ✗
- \$ *Sm* 219.10 ✗
- \$ *Sm* 293.00 ✗
- \$ *Sm* 191.50 ✗
- \$ *R* 107.00 ✗

Trans-cab Auto Services Pte Ltd

LAD2109-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 7220 Y

TOTAL	\$	11,090.70
25%	\$	2,772.68
	\$	8,318.03

Special Nett

1SET FRONT LH FENDER LINER CLIP	\$	nn	70.00	X
1SET FRONT RH FENDER LINER CLIP	\$	nn	70.00	X
1SET BUMPER CLIP FRT	\$	nn	80.00	50% X
1SET FRONT LH BUMPER SUPPORT CLIP	\$	nn	70.00	X
1SET FRONT RH BUMPER SUPPORT CLIP	\$	nn	70.00	X
1 RADIATOR GRILLE CLIP	\$	nn	60.00	✓
1 RADIATOR COVER CLIP	\$	nn	60.00	✓
1SET Front Licence Plate Number With Holder	\$	nn	200.00	45% X
1 HOOD INSULATOR CLIP	\$	nn	55.00	X

TOTAL	\$	735.00
--------------	-----------	---------------

TOTAL PARTS	\$	9,053.03
--------------------	-----------	-----------------

LABOUR

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of Parts,
Adjust And Realign The Same

\$ 3,500.00 50%

Putty And Spray Painting Of The Affected Portion.

\$ 3,500.00 66%

To remove and refit interior fittings, trimings, garnish,
fittings and other, to enable repair.

\$ nn 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 20%

To Rust-Proofing and apply undercoat Of The Affected
Areas.

\$ 250.00 30%

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMP 7230 y

To transfer of Front Bumper fittings, attachments and perform water seepage test.

\$ ~ 170.00 X

To check steering geometry and computer wheel alignment

\$ ~ 220.00 X

To transfer of Front Bonnet fittings, attachments and perform water seepage test.

\$ ~ 170.00 X

TOTAL \$ **8,530.00**

Over All Total \$ **17,583.03**

(PART-BY-PART) Repair Days

~~14~~ days

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey, is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	575K
Vehicle Details	
Vehicle No.:	SMP7220Y
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Sep 2021
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 STANDARD (AUTO)
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	1ZR0E04876
Chassis No.:	MR053REH604598923
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$18,787.00
Original Registration Date:	11 Oct 2019
First Registration Date:	11 Oct 2019
Transfer Count:	0
Actual ARF Paid:	\$18,787.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Oct 2029
PARF Rebate Amount:	\$14,090.00
Intended COE Rebate Details	
COE Expiry Date:	10 Oct 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$29,159.00
COE Rebate Amount:	\$23,593.00
Total Rebate Amount:	\$37,683.00

The information contained herein is correct as at 07 Sep 2021

OK