



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21009414/R1uf3e2 Date: 20/12/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	YP 355X
	Policy No.	Z20VC05006595	Coverage (\$)	0.00
	Claim No.	20/21/21/VC05/024926	Excess (\$)	700.00
	Assign From	ONG LI LI	Assign Date	07/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi canter feb21er	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	FEB21EA10734	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/85 R15	YOKOHAMA	7 mm
	L/H Front Tyre	195/85 R15	YOKOHAMA	7 mm
	R/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	7/7 mm
	L/H Rear Tyre	195/85 R15 (D)	YOKOHAMA	7/7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	03/09/2021	Inspection Date	08/09/2021
	Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
5a. Remarks				
	A) THE MARKET VALUE IS S\$39,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		22 Working Days	