



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21008609/R1vf3e2-1 Date: 04/10/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 4670J	Veh. Inspected	SGT 3380U	
Policy No.	Z20VC05006312	Coverage (\$)	0.00	
Claim No.	20/21/21/VC05/024851	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	08/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY CVT	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	MRHGD86907P030111	Colour	BLACK	
Odometer	300374 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R15	WINDFORCE	6 mm	
L/H Front Tyre	195/50 R15	WINDFORCE	6 mm	
R/H Rear Tyre	195/50 R15	WINDFORCE	6 mm	
L/H Rear Tyre	195/50 R15	WINDFORCE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2021	Inspection Date	17/08/2021	
Survey held at	U E MOTOR BLK 3006, UBI ROAD 1 #01-334 SINGAPORE 408700			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	