

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEONG WAI KWAN EDWIN
23 SARACA ROAD

SINGAPORE 807369

TEL: 96842603

ATTN:

Estimate No: MC1902143

Date: 07 Sep 2021

Policy No: GA420368/1

Veh Reg No: SJS188Z

Make/Model: TOYOTA LEXUS
ES300H CVT

Your Ref No: SJS188Z

Claim Type: Third Party

Accident Date: 06/09/2021

TP Veh Reg No: SJL4171G

Estimate Repair Cost to Vehicle No :SJS188Z

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 TAILAMP LH	1 PC	727.20	
2 TAILAMP LOWER BEAM LH	1 PC	125.40	
3 REAR BUMPER	1 PC	1,015.00	
4 REAR BUMPER SIDE RETAINER LH	1 PC	100.00	
5 REAR BUMPER CLIPS	15 PC	67.50	
6 REAR BUMPER REVERSE SENSOR OUTER LH	1 PC	490.80	
7 REAR BUMPER REVERSE SENSOR HOLDER	4 PC	57.20	
8 REAR BUMPER REFLECTOR LH	1 PC	75.60	
9 REAR BUMPER REINFORCEMENT	1 PC	654.60	
10 REAR BUMPER SPONGE	1 PC	139.50	
		3,452.80	
	Less 25%	863.20	2,589.60
LABOUR			
11 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	
12 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	120.00	
13 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	80.00	
14 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	120.00	
15 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	
16 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	500.00	
17 TO SPRAY REAR FENDER LH,REAR BUMPER.	1 PC	600.00	
		1,520.00	1,520.00


Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : LEONG WAI KWAN EDWIN
23 SARACA ROAD

SINGAPORE 807369

TEL: 96842603

ATTN:

Estimate No: MC1902143

Date: 07 Sep 2021

Policy No: GA420368/1

Veh Reg No: **SJS188Z**

Make/Model: TOYOTA LEXUS
ES300H CVT

Your Ref No: SJS188Z

Claim Type: Third Party

Accident Date: 06/09/2021

TP Veh Reg No: SJL4171G

Estimate Repair Cost to Vehicle No :SJS188Z

Description	Quantity	List Price S\$	Amount S\$
Total			S\$ 4,109.60
Add GST @ 7%			287.67
Total Amount Payable			S\$ 4,397.27

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND THREE HUNDRED NINETY SEVEN AND CENTS TWENTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY


Ah Lim Motor Company
AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	688A

Vehicle Details

Vehicle No.:	SJS188Z
Vehicle to be Exported:	No
Intended Deregistration Date:	06 Sep 2021
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES300H CVT S/R
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	2AR1398834
Chassis No.:	JTHBW1GG102110848
Maximum Power Output:	151.0 kW (202 bhp)
Open Market Value:	\$42,517.00
Original Registration Date:	31 Dec 2015
First Registration Date:	31 Dec 2015
Transfer Count:	0
Actual ARF Paid:	\$46,524.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Dec 2025
PARF Rebate Amount:	\$32,566.00

Intended COE Rebate Details

COE Expiry Date:	30 Dec 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$60,003.00
COE Rebate Amount:	\$25,887.00
Total Rebate Amount:	\$58,453.00

The information contained herein is correct as at 06 Sep 2021

OK