



Your Ref : CMTD2102691/RUC

Date: 15th Sep 2021

Our Ref : CS/SMO21009454/Ktf3e2

M/s Sompo Insurance Singapore PL

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGF 622R
INSURED VEHICLE: GBD 7881H
ACCIDENT ON 06/09/2021**

Instruction was received to inspect the vehicle Reg. No. SGF 622R. The inspection was conducted on 08/09/2021 at the premises of M/s Hiap Lek Automobile Trading, Blk 14 #01-19 Sector B Sin Ming Industrial Estate, Singapore 575658.

The following vehicle information was recorded:

Registration Number	: SGF 622R
Make/Model	: Toyota Vios 1.5E A
Year of Registration	: 2006
Body Colour	: Metallic Black
Chassis Number	: MR053HY4204178210
Engine Capacity	: 1497 cc

The vehicle sustained damages at the front and rear portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 27,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 22,546.00)
Nett Liability	<u>S\$ 4,454.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.