

## Hui Zhen (LKK Auto)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Friday, 3 December 2021 5:02 pm  
**To:** Hui Zhen (LKK Auto)  
**Subject:** RE: SNB 6285D Surveyed by Taufikh (CS/ASM21009495/T1uc)

Dear Hui Zhen,

Audit check done for SNB6285D without problem.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Hui Zhen (LKK Auto)  
**Sent:** Friday, 3 December, 2021 4:20 PM  
**To:** Simon Ho (LKKAuto)  
**Subject:** RE: SNB 6285D Surveyed by Taufikh (CS/ASM21009495/T1uc)

Dear Simon,

For your reaudit.

Best Regards,

**Hui Zhen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [huizhen@lkkauto.com](mailto:huizhen@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Simon Ho (LKKAuto)  
**Sent:** Monday, 29 November 2021 2:52 PM  
**To:** Hui Zhen (LKK Auto)  
**Subject:** RE: SNB 6285D Surveyed by Taufikh (CS/ASM21009495/T1uc)

Dear Hui Zhen,

Audit check done for SNB6285D, found parts prices need verification.

Best Regards,

**Simon Ho**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [simonho@lkkauto.com](mailto:simonho@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



*Save the Earth. Print only when necessary.*

---

**From:** Hui Zhen (LKK Auto)

**Sent:** Monday, 29 November, 2021 2:35 PM

**To:** Simon Ho (LKKAuto)

**Subject:** SNB 6285D Surveyed by Taufikh (CS/ASM21009495/T1uc)

Dear Simon,

For your audit.

Best Regards,

**Hui Zhen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [huizhen@lkkauto.com](mailto:huizhen@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)