

RE: GBF9421D

Koh, Victor-CK <Victor-CK.Koh@aig.com>

Thu 23/9/2021 4:56 PM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>

Hi Denise,

OK cost plus 10-15% is acceptable to proceed.

Thanks & Regards

Victor Koh

AIG

Claims Technical Controller

Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

Tel +65 6419 1785 | Fax +65 68357416

Victor-ck.koh@aig.com | www.aig.com

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Sent: Thursday, 23 September 2021 4:07 pm

To: Koh, Victor-CK <Victor-CK.Koh@aig.com>; SUR <sur@lkkauto.com>

Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>

Subject: [EXTERNAL] Re: GBF9421D

This message is from an external sender; be cautious with links and attachments.

Dear Victor,

Our surveyor has spoken to the repairer to repair on part by part, they are requesting for cost plus 15%.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Thursday, 23 September 2021 3:10 pm
To: SUR <sur@lkkauto.com>
Cc: Lim, Kok-Chong <Kok-Chong.Lim@aig.com>
Subject: GBF9421D

Hi,

Authorise repair. Re-inspection to be done for damage check and supplementary items / labour with clear photos.

FRONT BUMPER TOP BEAM, FRONT GRILLE – TOP, FRONT GRILLE BASE – Retake damage photos.
FRONT SUPPORT PANEL – To repair.

All old parts to be taken with the new parts during b/f paint photos. Part by part repair.

Thanks & Regards

Victor Koh
AIG

Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.