

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0193/2021
DATE : 12-OCT-2021

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 62222311 / 65063848
FAX : 62223547 / 65073849

OWNER'S NAME : HUANG YUNPING
ADDRESS : APT BLK 307D ANCHORVALE ROAD
#03-92
S(544307)
TELEPHONE NO : 96406931

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : P10464208R00
VEHICLE NO : SLT9517U
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YB31277
CHASSIS NO : JF1SJ5KC5JG099650
MILEAGE : 66268 KM
DATE IN : 12/10/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DANIEL A JUDE**
ACCIDENT DATE : 06/09/2021

Print Date : 27/10/2021
Print Time : 11:45:48

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT9517U

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST - SHB96T MS FIRST CAP INSURED		
2	ZZ/001	CONDUCT TP CLAIM MS FIRST CAP DATE:06/09/2021 TIME 2035HRS LOCATION:NEAR BISHAN MRT TAXI STAND		
3	ZZ/002	REPAIR/REPLACE FRT LH DOOR, LF WING MIRROR & PANEL	840.00	840.00
4	ZZ/003	RESPRAY FRT LH DOOR, LF WING MIRROR & PANEL	630.00	630.00
5	ZZ/004	TRANSFER DOOR MECHANISM (LH FRT)	200.00	200.00
6	ZZ/005	TO SUPPLY & INSTALL TINTED FILM (FRT LH WINDOW)	145.00	145.00
7	ZZ/006	SUNDRIES	20.00	20.00
		TOTAL LABOUR CHARGES	1835.00	1835.00

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT9517U

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	PNL COMPL DR F LH	60009SG0529P	720.00	✓		OK
2	GLASS ASSY DR F LH	61011SG211	504.00	✓		OK
3	WSTR OUT DR F LH	61280SG031	100.80	✓		OK
4	LAMP ASSY-SIDE TURN MIRROR LH	84401AJ010	102.00	✓		OK
5	TAPE DR SASH F F LH	90422SG010	5.40	✓		OK
6	TAPE DR SASH F M LH	90422SG030	18.00	✓		OK
7	TAPE DR SASH F R LH	90422SG050	18.00	✓		OK
8	R VIEW MIR UNIT RHL	91036SG854	475.20	✓		OK
9	COVER MIR BODY LH	91054AJ231	36.00	✓		OK
10	SIDE MIRROR LED SIGNAL SET	LPHSML-9005	500.00	✓		OK
SUB TOTAL			2479.40	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			495.88	0.00	0.00	0.00
GRAND TOTAL			1983.52	0.00	0.00	0.00
OVERALL TOTAL			1983.52			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLT9517U

NETT ITEM	2479.40
LESS 20 %	-495.88
NETT AMOUNT	1983.52
LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00
SPECIAL NETT AMOUNT	0.00
S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00
TOTAL LABOUR CHARGES	1835.00
TOTAL SPARE PARTS CHARGES	1983.52

TOTAL CHARGES	3818.52
ADD 7 % GST	267.30

GRAND TOTAL	4085.82
