

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKP 1398G
 at Workshop m/s: R.P.
 of: SK 2 7371R
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKP 1398G Yr Regn: 18/8/14
 Type: M Car / LM Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: KIA forte K3 c.c 1591
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 107296 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNAFX 411MF 5303702
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £ 344.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 7 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS 133F
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or nuxen
 Front: 6 Rear: 6
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 12/9/12 D.O.I. 13/9/12
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rec
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 23562
 Dep 106. N94 10438
 BJ involved
 21/9/14 45 @ 8500 confirmed w. to Alen.

Date/Time, File Pass to? Preli. Report
 Final Report

Days Of Repair: _____
 Resurvey No. of Trip: _____

Date/Time, File Return to?
 2)

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Survey Fee: _____
 Transportation: _____
) S + RS. SI
) Photos
) Others
)
 TOTAL

Report Format :
 Lump Sum / I.B.I.: (\$)

Hik Ask

Not Adhok

13/9/21

2/548500 / 7 days

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

VEHICLE No: SKP 1398G

1PC	BOOTLID	1491	DO/BUC	\$1,661.00	
2PCS	BOOTLID HINGES @\$150.00		R	\$300.00	X
1PC	BOOTLID REAR LOGO	45	REL	\$85.00	
1PC	BOOTLID 'CERATO' EMBLEM	42	REL	\$68.00	
1PC	BOOTLID 'FORTE' EMBLEM	40	REL	\$60.00	
1PC	BOOTLID 'K3' EMBLEM	40	REL	\$52.00	
1PC	BOOTLID C&C LOGO		REL	\$50.00	
1PC	BOOTLID INNER LOCK	112	TRIM	\$199.00	
1PC	BOOTLID WEATHERSTRIP	182	TRIM	\$281.00	
2PCS	BPPTLID REFLECTORS @\$725.00		11	\$1,450.00	X
1PC	BOOTLID INNER TRIM		11	\$281.00	X
1SET	BOOTLID INNER TRIM CLIPS		11	\$50.00	X
1PC	REAR BUMPER	688	DUS	\$1,250.00	
1PC	REAR BUMPER LOWER GARNISH	315	DUS	\$650.00	
2PCS	REAR BUMPER REFLECTORS @\$88.00	48	N/SIDE	\$176.00	1PC
2PCS	REAR BUMPER SIDE RETAINERS @\$60.00		11	\$120.00	X
1PC	REAR BUMPER REINFORCEMENT	495	CNE	\$515.00	
2PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$180.00	145 x 2 = 290	DO	\$360.00	
3PCS	REAR BUMPER REINFORCEMENT TOP BRACKETS @25.00		CNE	\$75.00	
2PCS	REAR BUMPER REINFORCEMENT LOWER BRACKETS @\$25.00		CNE	\$50.00	
1SET	REAR BUMPER CLIPS		REL	\$50.00	
1PC	REAR END PANEL	457	Body DS	\$691.00	
1PC	REAR END PANEL TOP GARNISH	188	TRIM	\$288.00	
2PCS	TAILLAMPS @\$1050.00	605 x 2 = 1210	CNE	\$2,100.00	
2PCS	TAILLAMP HOUSING PANELS @\$450.00		R	\$900.00	X
1PC	REAR FLOOR PANEL	1145.00	crumpled/buc	\$1,420.00	
1PC	REAR FLOOR PANEL TOP BOARD	385.00	merged	\$615.00	
2PCS	REAR FENDERS @\$1650.00		R	\$3,300.00	X
2PCS	REAR FENDER INNER TRIMS @\$355.00	262 x 2 = 524	De Join	\$710.00	
1PC	REAR EXHAUST		R	\$745.00	X
1PC	REAR EXHAUST HEAT SHIELD		STAF	\$122.00	
1PC	REAR WINDSCREEN MOULDING		TRIM	\$86.00	X
				\$18,760.00	
S.NETT					
1PC	REAR LICENCE PLATE		11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR		Shock	\$280.00	200
1PC	REAR END PANEL SEALANT		REL	\$50.00	
1SET	REAR FLOOR PANEL INSULATOR		REL	\$200.00	180
1PC	REAR WINDSCREEN SEALANT		11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL		11	\$50.00	X

10%

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	40
TO TRANSFER BOOTLID MECHANISM	\$100.00	60
TO DISMANTLE & REFIX CUSHON UPHOLSTERY	\$120.00	80
TO SPRAY RUST PROOFING	\$120.00	100
TO RESET & REPROGRAMME SYSTEM	11 \$100.00	X
TO DISMANTLE & REPLACED REAR EXHAUST	\$100.00	60
TO MOUNT VEHICLE ON CAR O-LINER	11 \$380.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$2,000.00	1400
TO PUTTY & SPRAY PAINTING	\$2,000.00	1200
TOTAL	\$24,490.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- A038
 10Z
 P-72342
 S-N-430
 L-2980
 106442
 A178