



Blk 1016 Yishun Industrial Park A, #01-218, Singapore 768758

Tel / Fax : 67542558

Company Reg No: 53076955K

ASSESSMENT OF DAMAGE AND COSTS

VEHICLE NO: FBQ8365G

A SPARE PARTS

Description LIST ITEMS	Qty	Assessed Condition	Repairer's Amount S\$	Our revised Amount S\$
Front Fork Set	1	Bent	900.00	450.00
Front Wheel Rim	1	Bent	480.00	240.00
Front Brake Dics	1	Bent	380.00	290.00
Handle Bar	1	Bent	195.00	195.00
Hand Guard	1	Sliced	380.00	380.00
Gear Pedal	1	Sliced	110.00	110.00
Engine Guard	1	Broken	500.00	500.00
Steering Cone/ Bearing	1	Broken	160.00	160.00

B) LABOUR

i) Transport cost + Labour Charges	250.00	200.00
------------------------------------	--------	--------

Total Cost of repairs (Total Cost of parts + labour cost) : \$ 3,355.00 \$ 2,525.00