

HSIAO Tony

NOT Authorised
Lbr
4585500/
4 days.

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

VEHICLE No: SMZ 9206Z

1PC	SLIDING DOOR N/S	DD/3enf 1861.25	\$1,969.10	✓
1PC	SLIDING DOOR GLASS REGULATOR N/S	177	\$485.50	X
1SET	SLIDING DOOR FRAME BLACK STICKER N/S	neu 100.00	\$105.00	✓
1PC	SLIDING DOOR INNER RUBBER N/S	177	\$288.20	X
1PC	SLIDING DOOR INNER TRIM BOARD N/S	21/Torn 945.10	\$1,099.10	✓
1PC	ROCKER PANEL GARNISH N/S	Torn/Cut	\$850.00	✓
1PC	ROCKER PANEL N/S	R	\$825.10	X
1PC	REAR FENDER N/S	R	\$1,466.20	X
1PC	REAR FENDER UNDER TRIM N/S	DIS 282-30	\$362.00	✓
1PC	REAR BUMPER	Torn 1066.10	\$1,685.10	✓
1PC	REAR BUMPER SIDE RETAINER N/S	177	\$105.00	X
1PC	REAR SHOCK ABSORBER N/S	177 392.10	\$425.10	✓
1PC	REAR WHEEL HUB BEARING N/S	277 450.50	\$850.00	✓
1PC	REAR AXLE BEAM	177	\$1,450.00	X
			\$11,965.40	

S.NETT

1SET	SLIDING DOOR INNER TRIM BOARD CLIPS N/S	neu	\$60.00	✓
1SET	REAR BUMPER CLIPS	neu	\$60.00	50
1PC	REAR SPORT RIM N/S	cut	\$900.00	450
1PC	REAR TYRE N/S	neu	\$200.00	X
1SET	ROCKER PANEL GARNISH	clips 177 neu	\$60.00	50

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REFIX REAR BUMPER REVERSE SENSOR	\$80.00	50
TO TRANSFER SLIDING DOOR MECHANISM N/S	\$120.00	60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$150.00	80
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$250.00	120
TO SPRAY RUST PROOFING	\$100.00	40
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	580
TO PUTTY & SPRAY PAINTING	\$1,500.00	800
	\$16,815.40	

TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-5947-35
252
P-4460-57
S.N- 610
L- 1830