

1.

SINGAPORE 068877

Insured Veh.

Assign From

Policy No.

Claim No.

MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD #16-01 CITY HOUSE

XE 4710Y

D21002562MFVS

ESTHER LIM

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R


PRE-REPAIR INSPECTION REPORT CS3/FCI21009580/Vvf3e2 Ref: 17/09/2021 Date: Code: FCI2 Policy Particulars :- (THIRD PARTY CLAIM) Veh. Inspected **SKN 2120U** Coverage (\$) 0.00 Excess (\$) 0.00 13/09/2021 Assign Date

Page No.:1 of 1

	_		_		
2.	Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	RU11301600	Colour	BLUE	
	Odometer	79208 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			

3.	Conditions of Tyres					
		Size	Make	Balance		
	R/H Front Tyre	215/60 R16	YOKOHAMA	6 mm		
	L/H Front Tyre	215/60 R16	YOKOHAMA	6 mm		
	R/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm		
	L/H Rear Tyre	215/60 R16	YOKOHAMA	6 mm		

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5.	General Information				
	Accident Date	09/09/2021	Inspect Date / Time 14/09/2021 (01:00 PM)		
	Survey held at	SPEEDWERKZ PTE LTD			
		13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807			

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

D)MARKET VALUE:\$67,000.00

Report Ref No. CS3/FCI21009580/Vvf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser