




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM21009583/T1uce2 Date: 19/10/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SH 9077C	Veh. Inspected	GBK 5225D
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M03HJY	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	13/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE DX 2.8 A	c.c	2754
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	GDH2012008050	Colour	WHITE
	Odometer	64574 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15	TOURADOR	6 mm
	L/H Front Tyre	195 R15	TOURADOR	6 mm
	R/H Rear Tyre	195 R15	TOURADOR	6 mm
	L/H Rear Tyre	195 R15	TOURADOR	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information				
	Accident Date	07/09/2021	Inspect Date / Time	14/09/2021 (04:00 PM)
	Survey held at	LKT GROUP PTE LTD 3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$5,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days

Report Ref No. CS3/ASM21009583/T1uce2

Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.