



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21009596/Utf3n2	Date: 27/09/2021
			Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	SKX 790X	Veh. Inspected	SMW 7312D
	Policy No.		Coverage (\$)	0.00
	Claim No.	C10011651/JM	Excess (\$)	0.00
	Assign From	IVY RATILLA	Assign Date	13/09/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	TOYOTA ALPHARD HYBRID (A)	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	AYH300104073	Colour	WHITE
	Odometer	79822 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	KAPSEN	6 mm
	L/H Front Tyre	215/60 R16	KAPSEN	6 mm
	R/H Rear Tyre	215/60 R16	KAPSEN	6 mm
	L/H Rear Tyre	215/60 R16	KAPSEN	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	10/09/2021	Inspection Date	13/09/2021
	Survey held at	EURO SUCCESS SERVICES PTE LTD 1 KAKI BUKIT AVENUE 6 #02-03 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	