



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TOKIO MARINE INSURANCE SINGAPORE LTD C/O SEDGWICK SINGAPORE PTE LTD 30 CECIL STREET, LEVEL 12 PRUDENTIAL TOWER SINGAPORE 049712			Ref: CS/SGK21009610/Kqf3e2 Date: 28/09/2021	Code: TMI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	MCST 1432	Veh. Inspected	GBC 5866X	
Policy No.	SGK: 6006122/EG	Coverage (\$)	0.00	
Claim No.	TMI Policy No. 21-LK001250-R01	Excess (\$)	0.00	
Assign From	HO YEW LIANG	Assign Date	14/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN (M)	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	JN1MG4E25Z0796895	Colour	WHITE	
Odometer	139002 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	8 mm	
L/H Front Tyre	195 R15X8	MICHELIN	8 mm	
R/H Rear Tyre	195 R15X8	MICHELIN	4 mm	
L/H Rear Tyre	195 R15X8	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE RECOVERED FROM FLOOD. MANY ELECTRICAL & MECHANISM PARTS FOUND DAMAGED AND CONTAMINATED BY FLOOD WATER AT THE TIME OF INSPECTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/09/2021	Inspection Date	14/09/2021	
Survey held at	K KIM HIN AUTOMOTIVE PTE LTD 160 SIN MING DRIVE #02-20 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	