

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT       |   |   |                |            |                         |  |
|------------------------------------|---|---|----------------|------------|-------------------------|--|
|                                    | MSIG INSURANCE (S) PTE LTD  |   |                | Ref:       | CS3/MSG21009631/R1qf3e2 |  |
|                                    | 4 SHENTON WAY<br>SINGAPORE 0688   |   | Date:          | 19/11/2021 |                         |  |
|                                    |   |   |                | Code:      | MSG                     |  |
| 1.                                 | Policy Particulars :- (THIRD PARTY CLAIM)   |   |                |            |                         |  |
|                                    | Insured Veh.  | PUBLIC LIABILITY                                      | Veh. Inspected |            | SGU 9067E               |  |
|                                    | Policy No.  | B 300445396 CAR                                       | Coverage (\$)  |            | 0.00                    |  |
|                                    | Claim No.   | 261912 CAR  | Excess (\$)    |            | 0.00                    |  |
|                                    | Assign From   | MARVIN CHIA   | Assign Date    |            | 14/09/2021              |  |
| 2. Vehicle Particulars & Condition |   |   |                |            |                         |  |
|                                    | Make & Model  | MITSUBISHI LANCER                                     | c.c            |            | 0                       |  |
|                                    | Engine No.  | HIDDEN  | Year of Reg.   |            | 2016                    |  |
|                                    | Chassis No.   | JMYSRCY1AGU004106                                     | Colour         |            | BLUE                    |  |
|                                    | Odometer  | 106750 KM   | Steering       |            | IN ORDER                |  |
|                                    | Brakes  | IN ORDER  | Modification   |            | SPORTS RIM              |  |
|                                    | General   | GOOD  |                |            |                         |  |
| 3. Conditions of Tyres             |   |   |                |            |                         |  |
|                                    |   | Size  | Make           |            | Balance                 |  |
|                                    | R/H Front Tyre  | 205/60 R15  | ADVANCE        |            | 6 mm                    |  |
|                                    | L/H Front Tyre  | 205/60 R15  | ADVANCE        |            | 6 mm                    |  |
|                                    | R/H Rear Tyre   | 205/60 R15  | ADVANCE        |            | 6 mm                    |  |
|                                    | L/H Rear Tyre   | 205/60 R15  | ADVANCE        |            | 6 mm                    |  |
| 4. Description of Damages          |   |   |                |            |                         |  |
|                                    | THE VEHICLE HAD   | AD COMPLETED ITS REPAIR WORKS.                        |                |            |                         |  |
| 5.                                 | General Information   |   |                |            |                         |  |
|                                    | Accident Date   | 27/08/2021  | Inspect Date / | Time       | 15/09/2021 ( 01:00 PM ) |  |
|                                    | Survey held at  | urvey held at 2A Woodlands Industrial Park D Street 2 |                |            |                         |  |
|                                    | Repairer -  |   |                |            |                         |  |
| 5a.                                | Remarks   |   |                |            |                         |  |
|                                    | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                |            |                         |  |

Report Ref No. CS3/MSG21009631/R1qf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser**