



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009635/R1uf3e2	
			Date: 20/12/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4919M	Veh. Inspected	SLQ 5374G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/09/21/2021	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	14/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID 1.8 CVT	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU203562057	Colour	WHITE	
Odometer	246338 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	FIRENZA	6 mm	
L/H Front Tyre	195/55 R15	FIRENZA	6 mm	
R/H Rear Tyre	195/55 R15	FIRENZA	6 mm	
L/H Rear Tyre	195/55 R15	FIRENZA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/09/2021	Inspection Date	15/09/2021	
Survey held at	LION CITY RENTALS PTE LTD 60 JALAN LAM HUAT# 04-35/36 CARROS CENTRE, 737869 SINGAPORE.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	