

1 of 2 ?

<

>

100%

Find | Next

100%

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD		Ref: CS/SMR21009638/Auf3	
60 WOODLANDS INDUSTRIAL PARK		Date: 14/09/2021	
E4SINGAPORE 757705		Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 1772T	Veh. Inspected	SDG 8225G
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/09/21/2024	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	14/09/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/09/2021	Inspection Date	15/09/2021
Survey held at	DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE, SINGAPORE 408619		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			