

SLN 6579S

<u>PARTS</u>				<u>S/N</u>		<u>LABOUR</u>		<u>SUPP (PARTS)</u>	
	\$1,317.80	\$0.00	\$0.00		\$600.00		\$200.00		\$0.00
	\$486.00	\$0.00	\$0.00		\$30.00		\$200.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$80.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$30.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		0%
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		<u>\$0.00</u>
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00	SUPP (SN)	
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$0.00		\$0.00		\$0.00
	\$0.00	\$0.00	\$0.00		\$630.00		<u>\$510.00</u>		<u>\$0.00</u>
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00					SUPP(LABOUR)	
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$0.00						
	\$0.00	\$0.00	\$1,803.80						
	\$0.00	\$0.00							
	\$0.00	\$0.00	\$1,803.80						
	\$0.00	\$0.00	75%						

TOTAL			
	\$1,352.85		\$0.00
	\$630.00		\$0.00
	\$510.00		<u>\$0.00</u>
SUPP	\$0.00	<u>TOTAL SUPP</u>	<u>\$0.00</u>
P/P	\$2,492.85	MAKE / MODEL	TOYOTA HARRIER (1986cc)
	\$2,492.85	MARKET VALUE	\$0.00
	80%	LTA REBATE	\$0.00
	\$1,994.28	NETT VALUE	\$0.00
L/S	\$2,000.00	RED	\$8,961.35
		TOTAL TP EST	\$10,961.35
		REPAIR DAYS	3

	\$0.00		<u>\$1,352.85</u>
--	--------	--	-------------------

<u>REMARKS</u>		
----------------	--	--