

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKJ7731U (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SLN6579S (TP veh)		PREMIUM CVT (A)
Date of Accident:	14/09/2021		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:\$	11,728.64	
Final Repair Cost	:\$	2,500.00	
Loss of Use	:\$	_____ days at \$0.00 per day	
Rental (if any)	:\$	3 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (Global Sum)	:\$	2,500.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____100____(%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: ____	
BOLA Liability: _____(%)		Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	New Hock Teck Motor Pte Ltd	:\$	2,500.00
2)		:\$	
3)		:\$	

JOANNE LEE KHANG MIN

13 Jan
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))