

29	REAR FENDER INNER TRIM	Could RH	2	\$ 640.00	\$ 1,280.00	640.485
30	REAR FENDER INNER UPPER TRIM	RH could	2	\$ 690.00	\$ 1,380.00	690 765
31	REAR FENDER INNER PANEL RH	Repis	1	\$ 485.00	\$ 485.00	x
32	REAR WHEEL HOUSE PANEL	Distord	1	\$ 945.00	\$ 945.00	689
33	REAR WHEEL HOUSE INSULATOR MATT RH	Repis	1	\$ 585.00	\$ 585.00	x
34	REAR WHEEL HOUSE UPPER PANEL RH	Repis	1	\$ 570.00	\$ 570.00	x
35	REAR FENDER AIR VENT RH	Miss: Could	1	\$ 95.00	\$ 95.00	-
36	REAR QUATER GLASS INNER PANEL RH	Repis	1	\$ 390.00	\$ 390.00	+
37	REAR QUATER GLASS C/W MOULDING RH	Repis	1	\$ 650.00	\$ 650.00	65
38	REAR DOOR RH	Repis	1	\$ 1,940.00	\$ 1,940.00	x
39	REAR DOOR FRAME INNER GARNISH RH	Repis	1	\$ 216.00	\$ 216.00	x
40	REAR DOOR FRAME WEATHERSTRIP RH	Repis	1	\$ 245.00	\$ 245.00	x
41	REAR DOOR INNER LOCK RH	Repis	1	\$ 390.00	\$ 390.00	x
42	REAR DOOR INNER TRIM RH	Repis	1	\$ 980.00	\$ 980.00	x
43	REAR DOOR WEATHERSTRIP RH	Repis	1	\$ 270.00	\$ 270.00	x
44	REAR END PANEL	Repis	1	\$ 970.00	\$ 970.00	x
45	REAR END PANEL TOP GARNISH	Delid	1	\$ 175.00	\$ 175.00	-
46	REAR FLOOR PANEL	Repis	1	\$ 1,890.00	\$ 1,890.00	x
47	REAR FLOOR PANEL TOP OUTER BOARD	Delid	1	\$ 460.00	\$ 460.00	x
48	REAR FLOOR PANEL TOP SIDE BOARD	RH Delid	2	\$ 190.00	\$ 380.00	190 105
49	REAR FLOOR PANEL TOP INNER BOARD	Repis	1	\$ 340.00	\$ 340.00	x
50	REAR STORAGE SPONGE BOX	Repis	1	\$ 380.00	\$ 380.00	x
51	REAR TOOLS TRAY TOP GARNISH	Repis	1	\$ 295.00	\$ 295.00	x
52	REAR TOOLS SPONGE TRAY	Delid	1	\$ 285.00	\$ 285.00	x
53	REAR CHASSIS FRAME RH	Repis	1	\$ 550.00	\$ 550.00	x
54	REAR CHASSIS TOP PANEL	Repis	2	\$ 365.00	\$ 730.00	x
55	REAR CHASSIS SIDE PANEL	Repis	2	\$ 540.00	\$ 1,080.00	x
56	REAR EXHAUST PIPE	Repis	1	\$ 1,650.00	\$ 1,650.00	x
57	REAR EXHAUST INSULATOR	Repis	1	\$ 250.00	\$ 250.00	x
58	REAR EXHAUST GASKET (SET)	Repis	1	\$ 200.00	\$ 200.00	x
59	REAR EXHAUST MOUNTING	Repis	4	\$ 85.00	\$ 340.00	x
60	REAR JACK COVER GARNISH	Repis	1	\$ 260.00	\$ 260.00	x
61	REAR ABSORBER RH	Best	1	\$ 390.00	\$ 390.00	x 295
62	REAR AXLE	Best	1	\$ 2,645.00	\$ 2,645.00	x 1988
63	REAR WHEEL HUB RH	Repis	1	\$ 490.00	\$ 490.00	x 298

9244.80
7355.84

TOTAL PRICE	\$ 36,649.80
LESS 20%	\$ 7,329.96
SUB TOTAL PRICE	\$ 29,319.84

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	BRAKE OIL	1	\$ 40.00	\$ 40.00
2	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
3	REAR BUMPER CLIP (SET)	1	\$ 50.00	\$ 50.00

4	REAR BUMPER LED LIGHT (SPECAIL TYPE)	1	\$ 180.00	\$ 180.00	120
5	TAIL GATE INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00	+
6	TAIL GATE WINDSCEEN SEALANT	1	\$ 80.00	\$ 80.00	+
7	TAIL GATE WINDSCEEN INNER SEAL	1	\$ 60.00	\$ 60.00	+
8	REAR FENDER SEALANT	1	\$ 80.00	\$ 80.00	60
9	REAR FENDER INNER COWLING (SET)	1	\$ 50.00	\$ 50.00	20
10	REAR FENDER INNER TRIM CLIPS (SET)	1	\$ 50.00	\$ 50.00	30
11	REAR WHEEL HOUSE PANEL SEALANT	1	\$ 80.00	\$ 80.00	60
12	REAR QUATER GLASS SEALANT RH	1	\$ 60.00	\$ 60.00	40
13	REAR QUATER GLASS INNER SEAL RH	1	\$ 40.00	\$ 40.00	+
14	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	+
15	REAR END PANEL TOP GARNISH CLIPS (SET)	1	\$ 30.00	\$ 30.00	10
16	REAR FLOOR PANEL INSULATION SEAL	1	\$ 350.00	\$ 350.00	+
17	REAR FLOOR BOARD BOTTOM GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00	+
18	REAR WHEEL TYRE RH	1	\$ 480.00	\$ 480.00	+
19	REAR WHEEL RIM RH	1	\$ 1,200.00	\$ 1,200.00	400
20	REVERSE SENSOR	1	\$ 220.00	\$ 220.00	200
21	REVERSE CAMERA	1	\$ 450.00	\$ 450.00	+

TOTAL \$ 3,800.00 1010

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	1400
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,000.00	1000
3	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
4	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	+
5	REAR CHASSIS ALIGNMENT	\$ 250.00	+
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	+
7	TRANFER TAILGATE MECHANISM	\$ 80.00	+
8	TRANFER REAR DOOR MECHANISM RH	\$ 80.00	+
9	REMOVE AND REFIX REAR FENDER GLASS RH	\$ 120.00	60
10	REMOVE AND REFIX FUEL TANK TO FACILIATE FENDER REPLACEMENT	\$ 100.00	+
11	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	300

12	FOUR WHEEL ALIGNMNET	\$ 120.00	80
13	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	80
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2570

TOTAL \$ 6,440.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 33,119.84
 TOTAL LABOUR COST : 6440
 TOTAL REPAIR COST : \$ 39,559.84

Admin Lj
 w/s 15/09/21.
 10 Days -

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

total: 91375.84

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 9151 6861

w/s: 9-1K
 9-1K.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: