



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21009688/Euf3e2	
			Date: 30/09/2021	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SG 6141A	Veh. Inspected	PH 6868S	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/09/21/7011	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	16/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YUTONG ZK6116HE	c.c	6690	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	LZYTBE62G1055158	Colour	MULTI COLOUR	
Odometer	309977 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
L/H Front Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
R/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
L/H Rear Tyre	295/80 R22.5	BRIDGESTONE	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	13/09/2021	Inspection Date	20/09/2021	
Survey held at	WOODLANDS TRANSPORT SERVICE PTE. LTD. 8 GUL CIRCLE SINGAPORE 629564			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>1 Working Days</b>	