

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0424/2021/GW
DATE : 18-May-21
WIP : 28002

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 15/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - Johnny Boo

2-Nov-21

OWNER'S NAME : ORIENTAL SHEET PILING PTE LTD
ADDRESS : 23 NAMLY DRIVE
SINGAPORE 267437
TELEPHONE : HP +65 83666633
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070171472
VEHICLE NO : **SGZ 6633 P**
MODEL CODE : AUDI Q8 3.0 TFSI QU TIP
MODEL YEAR : 22/11/2018
ENGINE NO : DCB047111
CHASSIS NO : WAUZZZF1KD006122
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-May-21
PLACE OF ACCIDENT : CARPARK AT TANJONG PAGAR BLK 6

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGZ 6633 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,350.00	\$ 600.00
3	TO RESPRAY REAR BUMPER , REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS.	\$	3,200.00	\$ 1,700.00
4	TO RENEW REAR EXHAUST SILENCER AND ALIGN TO POSITION.	S/N \$	480.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 5,582.00	\$ 2,852.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 6633 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER-UPPER	1	\$ 1,362.00	
2	REAR BUMPER-LOWER	1	\$ 2,669.00	
3	REAR BUMPER FIXING PARTS	1	\$ 170.00	
4	REAR BUMPER SIDE TRIM-LH	1	\$ 86.00	
5	REAR BUMPER CENTER TRIM	1	\$ 129.00	
6	REAR BUMPER FILLER TRIM-CENTER	1	\$ 423.00	\$ 338.40
7	REAR BUMPER SPOILER - DARK CHROME MATT	1	\$ 815.00	\$ 651.60
7	REAR EXHAUST TRIM PLATE -LH	1	\$ 95.00	\$ 75.84
8	REAR EXHAUST TRIM -LH	1	\$ 244.00	\$ 195.20
9	REAR BUMPER LOWER SPOILER	1	\$ 575.00	\$ 460.00
10	REAR BUMPER DIFFUSER	1	\$ 1,261.00	
11	REAR BOOT LID CONTROL UNIT	1	\$ 411.00	
12	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,417.00	
13	REAR BUMPER SEAL-LH/RH	2	\$ 28.00	
14	REAR BUMPER RETAINER PLATE	1	\$ 182.00	
15	REAR BUMPER GUIDE SECTION-CENTER	1	\$ 142.00	
16	REAR BUMPER GUIDE SECTION-LH LOWER	1	\$ 75.00	
17	REAR BUMPER GUIDE SECTION-LH UPPER	1	\$ 67.00	
18	RETAINER FOR AERIAL-LH	1	\$ 26.00	
19	TELEPHONE AERIAL	1	\$ 174.00	
20	REAR REFLECTOR LIGHT-LH	1	\$ 136.00	
SUB TOTAL SPARE PARTS		:	\$ 10,487.00	\$ 1,721.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 6633 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 1,774.00
21	REAR SILENCER	1	\$ 2,344.00	
22	REAR SILENCER MUFFLER CLAMP	1	\$ 121.00	
23	REAR SILENCER HANGER	1	\$ 60.00	
24	REAR WHEEL COVER-LH/RH	2	\$ 756.00	\$ 602.40
25	SUNDRIES		\$ 250.00	52.96
TOTAL SPARE PARTS		:	\$ 14,018.00	\$ 2,376.40
TOTAL LABOUR CHARGES		:	\$ 5,582.00	\$ 2,852.00
GRAND TOTAL		:	\$ 19,600.00	\$ 5,228.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-29/04/21

BL-02/11/21

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT