Our Ref:

YN8594E190527

Your Ref:

Lonpac Insurance Berhad 300 Beach Road #17-04 / 07 The Concourse Singapore 199555

Attn: Motor Claims Department

Dear Sir / Madam	
Traffic Accident Along Junction Of Lorong 27 And Sims Avenue Involving YN8594E and SKE125S On 27/05/2019	_
We/I, Goldbell Leasing Pte Ltd (NRIC / ROC No: 199001196N), the region of the above accident. Our/my Lonpac authorized appraiser and we / I based our / my claims S\$_535-72 being the repair for _02 Days (Strictly on a Without	y vehicle was surveyed by " s on his recommendation for
We/I have ascertained that you were the insurers of the driver of m/vehic same was involved in the aforesaid accident with our/my m/vehicle - $\underline{\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ $	A Commence of the second secon
We/I whereby you are the insurers of m/vehicle <u>SKE125S</u> and the drive by the negligence of your insured and as a result there of our / my m/vehi suffered loss and damage as follows:	
Cost of repairs LOU for pre-repair notice 02 days @ S\$ 120-00 [2986 cc Fridge Box Truck] LOU Fee for02 days @S\$120-00 [2986 cc Fridge Box Truck] Rental Fee Invoice No: GIA / LTA search fee Towing Fee (Cash Sale No) Survey Fee	535-72 240-00 240-00
Total Amount S\$	1,017-72
We/I enclose herewith copies of the supporting documents for vehicle no. (i) Motor Accident Report & Documents; (ii) Repair Invoices;	YN8594E as follows:-
Kindly look into the matter and let us/me hear from you on the settlement as possible.	at of our/my claims as soon
Please remit us/me your settlement sum in favor of M/s Liu's Brother A Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki	
Thank you.	
Yours faithfully,	

Date: 28/09/2021

The owner of m/vehicle YN8594E

Messers Goldbell Leasing Pte Ltd
cc. Liu's Bro Auto Engineering Workshop

LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

Invoice/Ref No: YN8594E190527

Quotation /

535.72

ROB No: 53291793J . Tel: 6741-1730 / 731 . Email: liusbro@ymail.com Final Bill Customer Name: MS First Capital Insurance Limited Date: 28-09-21 Address Motor Claims Department Vehicle No: YN8594E 36 Robinson Road #16-01 City House Model/Make: Mitsubishi Canter FEB21CR3SDEB Singapore o68877 Revised Original

No.	Descriptions Of Parts	 uotation / stimation		 Cost Of Repair
1	Rear Rh Tail Lamp	\$ 194.30	1	\$ 194.30
	Part Less 25%			\$ 48.58
	Total Parts After Less 25%			\$ 145.72
2	Rear Rh Support Rubber "Big"	\$ 250.00	SN	\$
3	Support Rubber "Small"	\$ 180.00	SN	\$
4	Bumper	\$ 600.00	SN	\$
	To check all wiring & electrical component for proper function	\$ 40.00		\$ 20.00
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etcs	\$ 500.00		\$ 250.00
	To putty & spray painting & including touch up paint on accident affected areas	\$ 200.00		\$ 120.00

Total Parts & Labour of estimate for damaged vehicle

\$ 1,964.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

Item

M/s Liu's Bro Auto Engrg Wks

INSURER ENQUIRY Find

insurer

Vehicle reg. no.

SKE125S

Date of Accident

27/05/2019 🛗

Reset

% RESULT & RECEIPT

TP Insurer Enquiry Insurance Lonpac Insurance Bhd Period of Insurance 01/01/2019 - 31/12/2019 Requested By Susan Low (Liu's Brother Auto... Requested Date 15/09/2021 14:37

Payment details

Request Amount: **\$\$1.87**GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): \$\$2

General Insurance Association

Records Management Centre GST Registration No: **M400017735**