



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21009712/Uqf3e2	
			Date: 30/11/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJZ 1505Z	Veh. Inspected	SKC 3777B	
Policy No.	D21MTPV01008910	Coverage (\$)	0.00	
Claim No.	CMTD2102475/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	16/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER RANGE ROVER EVOQUE (A)	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	SALVA2AG6FH984087	Colour	WHITE	
Odometer	128250 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	6 mm	
L/H Front Tyre	235/60 R18	PIRELLI	6 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	17/08/2021	Inspection Date	21/09/2021	
Survey held at	1ST AUTO PRO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	