

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0760/2021/TF
DATE : 15-Sep-21
WIP : 44526

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR LAU MA CHUN JEFFREY
ADDRESS : 3 MALMORAL ROAD
#03-04
SINGAPORE 259785
TELEPHONE : HP +65 90011801
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070059542-01
VEHICLE NO : **SMT 2092 L**
MODEL CODE : AUDI Q3 1.4 TFSI
MODEL YEAR : 30/3/2025
ENGINE NO : CZD 891771
CHASSIS NO : WAUZZZF34L1079459
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 10/9/201
PLACE OF ACCIDENT : CARPARK AT 3 BALMORAL ROAD

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 2092 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00 ✓	
2	TO DISMANTLE AND RENEW RHS FRONT DOOR. TO REPAIR RHS SILL PANEL AND DOOR ENTRANCE. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	S/N \$	2,400.00 550	
3	TO RESPRAY RHS FRONT DOOR , DOOR COVER, RHS SILL PANEL, DOOR ENTRANCE AND RHS WING MIRROR COVER.	\$	3,500.00 950	
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$ 6,492.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 2092 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - RH	1 \$	2,816.00	bt ✓
2	FRONT DOOR OUTER SEAL - RH	1 \$	166.00	ng ✓
3	FRONT DOOR CATCH - RH	1 \$	120.00	X
4	FRONT DOOR WINDOW REGULATOR - RH	1 \$	282.00	?
5	FRONT DOOR WINDOW REGULATOR MOTOR - RH	1 \$	289.00	X
6	FRONT DOOR CONTROL UNIT - RH	1 \$	400.00	X
7	FRONT DOOR LOWER COVER - RH	1 \$	370.00	de ✓
8	SILL TRIMSTRIP - RH	1 \$	556.00	X
9	WING MIRROR MOUNTING - RH - damaged prop	1 \$	2,065.00	bt ✓
10	WING MIRROR COVER - RH	1 \$	191.00	?
11	WING MIRROR - RH	1 \$	998.00	X
12	TYRE PRESSURE STICKER	1 \$	30.00	X
13	STONE CHIP TREATMENT	S/N \$	180.00	X
14	SUNDRIES	\$	300.00	?
TOTAL SPARE PARTS		:	\$	8,763.00
TOTAL LABOUR CHARGES		:	\$	6,492.00
GRAND TOTAL		:	\$	15,255.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Tan Jiah 97495749*
SURVEYED DATE : *16/9/21 @ 245pm*
AUTHORISED DATE : *Not authorise, Request*
EXCESS COST : *Exp: to be advise*
LIABILITY : *03 days*
REMARKS : ** Resurvey before paint*
Tan Jiah to 16/9/21

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT