




Service Requests

Messages

Claims



Service Request Details

Claim	S1M03H4N
Reference	CS3/ASM21009735/Bqce2 
Loss Date	1 September 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Contract Type	VFX
Contract Name	VFX

Actions

Next Step Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident Vehicle Registration #	SDV4007S
Make	TPVD Volvo
Model	Xc60
Vessel/Truck/Flight	
Vessel	

Type of
Loss

Third Party Vehicle
Damage

Report Date 2 Sep 2021 5:55:22 PM

Request 17
Date September 2021

17
September 2021 11:16 AM

Due Date

Services Pre-Repair Survey

Insured

COMFORT TRANSPORTATION PTE
LTD 383 SIN MING DRIVE, 575717,
Singapore 65551188

Truck

Flight

Service Address

, , ,

Primary Contact

Primary Contact/Insured

COMFORT
TRANSPORTATION PTE LTD 383 SIN MING
DRIVE, 575717, Singapore
65551188

Claim Handler

TEO Kitty
kitty.teo@axa.com.sg

Additional Instructions [\(expand\)](#)

Messages2

Invoices

History

Documents

Assessment

Metrics




Notes






Document Type







Document SubType




+ Upload Documents

Already Attached

NAME	DATE UPLOADED			
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 S1M03H4N_[CTPL-Reported - TPPD]_Accident Involving SHA7895M & SDV4007S_along_CROSS JUNCTION OF BRAS BASAH RD AND NTH BRIDGE RD on 01/09/2021 21:30_PersonalAutoLine	Other	Other	do not reply	
 S1M03H4N_TP REF:CL/210930/T/HL_Accident Involving SHA7895M & SDV4007S_along_CROSS JUNCTION OF BRAS BASAH RD AND NTH BRIDGE RD on 01/09/2021 21:30_PersonalAutoLine	Other	Other	do not reply	
 ASM-LKKInvoice-AC2106939.pdf.pdf	Email Sent			

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
		Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	7 October 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	7 October 2021
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 October 2021
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 October 2021
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	7 October 2021
 AXA Immediate Advice - SDV4007S (PRS).pdf.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 October 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SURVEYOR APPOINTED.msg.msg	Letters and Correspondence	Solicitor / Advocate	VISHNU BATHAM Shekhar	17 September 2021
 Service appointment in Vendor Portal claim S1M03H4N for vehicle SDV4007S.html.html	Email Sent		VISHNU BATHAM Shekhar	17 September 2021
 LIST OF SURVEYOR SENT.msg.msg	Letters and Correspondence	Solicitor / Advocate	VISHNU BATHAM Shekhar	17 September 2021
 CTPL-REPORTED-TPPD.msg.msg	Letters and Correspondence	Policy Holders / Insured	VISHNU BATHAM Shekhar	17 September 2021
 EMAIL TP REG.pdf.pdf	Letters and Correspondence	Solicitor / Advocate	VISHNU BATHAM Shekhar	17 September 2021
 EMAIL TP REG.msg.msg	Letters and Correspondence	Solicitor / Advocate		

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
			VISHNU BATHAM Shekhar	17 September 2021
 GIA SDV4007S TP.pdf.pdf	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	17 September 2021
 OI VIDEO.mp4	Evidence	Videos	TEO Kitty	17 September 2021
 SHA7895M INSD GIA.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	2 September 2021

«

1

»