

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT |   |   |                |                        |                         |
|------------------------------|---|---|----------------|------------------------|-------------------------|
|                              | LONPAC INSURAN  |   | Ref:           | CS3/LPC21009747/Gvf3e2 |                         |
|                              | 300 BEACH ROAD<br>SINGAPORE 1995  |   | Date:          | 01/10/2021             |                         |
|                              |   |   |                | Code:                  | LPC2                    |
| 1.                           | Policy Particulars :- (THIRD PARTY CLAIM)   |   |                |                        |                         |
|                              | Insured Veh.  | GBF 8317D   | Veh. Inspected | l                      | SLE 909K                |
|                              | Policy No.  | Z21VC05005908   | Coverage (\$)  |                        | 0.00                    |
|                              | Claim No.   | 21/21/21/VC05/024964  | Excess (\$)    |                        | 0.00                    |
|                              | Assign From   | GERALD POH  | Assign Date    |                        | 17/09/2021              |
| 2.                           | . Vehicle Particulars & Condition   |   |                |                        |                         |
|                              | Make & Model  | NISSAN SYLPHY 1.6   | c.c            |                        | 1598                    |
|                              | Engine No.  | HIDDEN  | Year of Reg.   |                        | 2016                    |
|                              | Chassis No.   | MNTBBAB17Z0027489   | Colour         |                        | RED                     |
|                              | Odometer  | 47870 KM  | Steering       |                        | IN ORDER                |
|                              | Brakes  | IN ORDER  | Modification   |                        | SPORTS RIM              |
|                              | General   | GOOD  |                |                        |                         |
| 3. Conditions of Tyres       |   |   |                |                        |                         |
|                              |   | Size  | Make           |                        | Balance                 |
|                              | R/H Front Tyre  | 205/55 R16  | BRIDGESTONE    |                        | 6 mm                    |
|                              | L/H Front Tyre  | 205/55 R16  | BRIDGESTONE    |                        | 6 mm                    |
|                              | R/H Rear Tyre   | 205/55 R16  | BRIDGESTONE    |                        | 6 mm                    |
|                              | L/H Rear Tyre   | 205/55 R16  | BRIDGESTONE    |                        | 6 mm                    |
| 4. Description of Damages    |   |   |                |                        |                         |
|                              | THE VEHICLE SUS   | STAINED DAMAGES AT THE FRONT PORTION.                           |                |                        |                         |
| 5.                           | General Information   |   |                |                        |                         |
|                              | Accident Date   | 16/09/2021  | Inspect Date / | Time                   | 29/09/2021 ( 12:00 PM ) |
|                              | Survey held at  | CARSMITH PTE LTD  |                |                        |                         |
|                              |   | BARTLEY BIZ CENTRE,13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807 |                |                        |                         |
| 5a.                          | a. Remarks  |   |                |                        |                         |
|                              | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |   |                |                        |                         |

Report Ref No. CS3/LPC21009747/Gvf3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

**Automotive Assessor**