

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0766/2021/ZK
DATE : 17-Sep-21
WIP : 44759

Justin.
\$3877.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY
YOUR INSURED VEH NO : SLH 8844 U

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MRS OOI TEE ANN
ADDRESS : 515 BEDOK RESERVOIR ROAD
#01-61
SINGAPORE 479274
TELEPHONE : HP +65 9825 1345
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 11017806
VEHICLE NO : SMF 3007 B
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 31/10/2018
ENGINE NO : CZE 802080
CHASSIS NO : WAUZZZ8V7J1083226
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Sep-21
PLACE OF ACCIDENT : JUNCTION OF TOSCA STREET AND FIGARO STREET

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL 6366 2323 FAX 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 3007 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$ 280.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$ 1,050.00	550
3	TO RESPRAY REAR BUMPER	\$ 900.00	550
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 2,422.00	

CB 1228W

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL 6366 2323 FAX 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 3007 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Delud</i>	1	\$ 1,944.00 ✓	1555.20
2	FRONT BUMPER FIXING PARTS <i>Not</i>	1	\$ 193.00 +	
3	REAR BUMPER GUIDE SECTION - LH / RH <i>Not</i>	2	\$ 32.00 +	
4	REAR SPOILER <i>Not Not</i>	1	\$ 237.00 +	
5	REAR LIGHT REFLECTOR - LH / RH <i>2</i>	2	\$ 82.00 +	
6	REAR BUMPER REINFORCEMENT BAR	1	\$ 603.00 +	
7	REAR BUMPER BRACKET - LH / RH <i>Not</i>	2	\$ 56.00 +	
8	REAR PARKING AID SENSOR	2	TBC	
9	REAR PARKING AID SENSOR SEAL	4	\$ 14.00 +	
10	SUNDRIES <i>Not Not</i>	1	\$ 200.00 +	
TOTAL SPARE PARTS		:	\$ 3,361.00	
TOTAL LABOUR CHARGES		:	\$ 2,422.00	
GRAND TOTAL		:	\$ 5,783.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



SEE VOLE BLE TLD

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2320 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *20/08/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 13 days* *04 Days*
H/S

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



LEE AUTO PTE LTD

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: sales@premiumauto.com.sg / claims@premiumauto.com.sg

Justin.

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/Q766/2021/ZK
6-Oct-21
TONY
1 of 1
SMF 3007 B
AUDI A3 SEDAN 1.4 TFS

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labours

- | | |
|---|-------------------------------|
| 1 | TO REPAIR REAR END PANELLING |
| 2 | TO RESPRAY REAR END PANELLING |

\$	700.00	250
\$	1,000.00	550

GRAND TOTAL

\$ 1,700.00

For Premium Automobiles Pte Ltd

Adrian L

06/10/21

SLG



Authorised Signature



PREMIUM AUTOMOBILES PTE LTD