

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref: CS/ICS21009767/Btf3		
10 EUNOS ROAD 8		Date: 20/09/2021		
SINGAPORE POST CENTRE #09-04A				
SINGAPORE 408600		Code: ICS		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 8751Y	Veh. Inspected	SLQ 8822K	
Policy No.		Coverage (\$)	0.00	
Claim No.	DMPC2100324H.02	Excess (\$)	0.00	
Assign From	LIU CHUN CHEONG	Assign Date	20/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/09/2021	Inspection Date	20/09/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				