



STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042 EUROKARS GROUP
ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE (SINGAPORE)

3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
ATTN.: MOTOR CLAIMS
FAX:

NAME:

ADDRESS:

TEL:

WIP: 21921

EXCESS:

DATE: 16-Sep-21

VEH NO:	SJP9088K	DATE IN:		CONTACT PERSON:		JOB:	63310682
CHASSIS NO:	WP0ZZZ97ZJL117689	MILEAGE:		TYPE OF CLAIM:		OWN DAMAGE	
MODEL:	Panamera	DATE REG.:	7-Nov-18	POLICY NO.:			

NATURE OF WORKS

Parts Description

S/NO	QTY	1ST	SUPP	REVISED	PRICES
1	FRONT BUMPER <i>scr</i>	1			\$ 2,237.60
2	FRONT GRILLE CENTER <i>scr</i>	1			\$ 308.50
3	FRONT GRILLE LH ?	1			\$ 129.00
4	FRONT GRILLE LH OUTER TRIM <i>scr</i>	1			\$ 99.30
5	FRONT GRILLE DISC SUPPORT LH ?	1			\$ 94.50
6	FRONT GRILLE LH DISC <i>9scr</i>	1			\$ 127.70
7	HOUSING FOR CAMERA <i>X</i>	1			\$ 43.00
8	SUPPORT BRACKET FOR CAMERA <i>X</i>	1			\$ 40.20
9	SENSOR ?	6			\$ 1,511.40
10	SENSOR GASKET <i>scr</i>	6			\$ 18.60
11	NUMBER PLATE BRACKET <i>MIS</i>	1			\$ 85.00
12	HEADLIGHT BRACKET LH ?	1			\$ 85.80
13	FRONT BUMPER RETAINER LH <i>X</i>	1			\$ 38.80
14	FIXING DEVICE <i>scr</i>	2			\$ 27.40
15	FRONT BUMPER REINFORCEMENT ?	1			\$ 1,099.90
16	FRONT BUMPER SPONGE ?	1			\$ 83.90
17	ADDITIONAL HEADLAMP LH <i>scr</i>	1			\$ 757.30
18		0			\$ -
TOTAL PARTS					\$ 6,787.90
TOTAL PARTS COST					\$ -

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							
Labour Description							
1	TO REMOVE /REPLACE FRONT BUMPER, REINFORCEMENT & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.					1560	\$ 3,120.00
2	TO RESPRAY FRONT BUMPER.					1300	\$ 1,300.00

	TO SUPPLY FRONT LICENCE PLATE WITH CASING <i>Cm /</i>			NETT	\$ 70.00
	TO TRANSFER THE FRONT SENSORS.			<i>150</i>	\$ 300.00
5	TO TRANSFER THE FRONT CAMERA.			<i>100</i>	\$ 300.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			<i>150</i>	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			NETT	\$ 600.00
8	SUNDRIES.			NETT	\$ <i>20</i> 50.00
				TOTAL LABOUR	\$ - \$ 6,190.00
				TOTAL PARTS	\$ - \$ 6,787.90
				TOTAL	\$ - \$ 12,977.90
				LESS EXCESS	\$ - \$ -
				TOTAL AFTER EXCESS	\$ - \$ 12,977.90
				GST 7%	\$ - \$ 908.45
				GRAND TOTAL	\$ - \$ 13,886.35

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068
4 days
£ 22/09/21 @ 1040
EXCESS: 2000
Rever
Resy before paint