



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BERKSHIRE HATHAWAY SPECIALTY INSURANCE COMPANY Ref: CS/BSH21009782/Guf3e2
39 ROBINSON ROAD #10-01 Date: 12/11/2021
ROBINSON POINT
SINGAPORE 068911
Code: BSH

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	WC223K-FORKLIFT	Veh. Inspected	GBG 2465T
Policy No.		Coverage (\$)	0.00
Claim No.	LI2109091890/CG	Excess (\$)	0.00
Assign From	CELINE GOH	Assign Date	20/09/2021

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV350	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JN1MC2E26Z0008099	Colour	WHITE
Odometer	65131 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	FALKEN	6 mm
L/H Front Tyre	195 R15	FALKEN	6 mm
R/H Rear Tyre	195 R15	FALKEN	6 mm
L/H Rear Tyre	195 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/09/2021	Inspection Date	21/09/2021
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**