



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Ref: CS3/FCI20010742/Etf3e2-1

Date: 05/10/2021

Code: FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SHC 432B	<b>Veh. Inspected</b>	FBK 351E
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20003965MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ERIC WOO	<b>Assign Date</b>	20/09/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	HONDA CBR250R	<b>c.c</b>	250
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015
<b>Chassis No.</b>	MLHMC41A2B5004304	<b>Colour</b>	BLACK
<b>Odometer</b>	84104 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	100/80-17	PIRELLI	4 mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>	140/70-17	PIRELLI	4 mm
<b>L/H Rear Tyre</b>			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	28/09/2020	<b>Inspection Date</b>	19/10/2020
<b>Survey held at</b>	GARAGE 13 PTE LTD 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE.		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**