

aint Work

Code	Description	SYSTEM AZT	Time Basis 10 WU/h	
			WU	Price SGD
	FRONT GRILLE NEW PART PAINT K1R		7.0	
	FRONT PANEL TRIM NEW PART PAINT K1R		5.0	

Paint Material Per Part

Code	Description	Price SGD
0828	R/F MUD FLAP BRKT SURFACE PAINT	0.53
0887	L/F CORNER PANEL NEW PART PAINTING	7.25
0888	R/F CORNER PANEL NEW PART PAINTING	7.25
0900	FRONT PANEL CPL NEW PART PAINTING	33.21
0931	LOWER FRONT PANEL SURFACE PAINT	3.87
2810	CAB SUPPORT SURFACE PAINT	6.69
2811	FRONT TORSION BAR SURFACE PAINT	2.29
2813	L/CAB ATTACHMENT SURFACE PAINT	0.70
2814	R/CAB ATTACHMENT SURFACE PAINT	0.70
4242	R/F WHEELARCH PANEL SURFACE PAINT	1.76
0410	FRONT GRILLE NEW PART PAINT K1R	23.73
032	FRONT PANEL TRIM NEW PART PAINT K1R	12.91

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		82.0	
Preparation Main Work Metal	1.70	17.0	71.40
Preparation Comp. Work Plastic	0.30	3.0	12.60
Total	10 WU/h	102.0	428.40

Material Cost - Paint

	Price SGD
New Part Painting	47.71
New Part Painting - Plastic K1R	36.64
Surface-/Blend Paint	16.54
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	127.99

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01	
					Price SGD
0257	FRONT NUMBER PLATE	NO NUMBER	Original	MIS	30.00 ✓
0258	FRT NO PLATE REINF	NO NUMBER	Original	NIP	20.00 X
0281	FRONT BUMPER	MC978515	Original	R	670.00 ✓
0282	CENTRE BUMPER COVER	ML301161	Original	NIP	55.00 X
0283	L/F BUMPER BRACKET	MK617973	Original	R	135.00 ✓
0284	R/F BUMPER BRACKET	MK617974	Original	R	135.00 ✓
0289	L/F BUMPER CORNER	MK617983	Original	Di	248.00 ✓
0290	R/F BUMPER CORNER	MK617989	Original	MIS	248.00 ✓
0319	L/COVER BRACKET	MK580695	Original	NIP	60.00 X
0320	R/COVER BRACKET	MK580695	Original	NIP	60.00 X
0410	FRONT GRILLE	MC975208	Original	CAT	750.00 ✓

Code	Description	Part Number	Part Source	Price SGD
0431	FRONT MANUFACT BADGE	MK546616	Original	58.00
0432	BADGE	MK546617	Original	85.00
0433	BADGE	MK675497	Original	58.00
0561	LEFT HEADLAMP ASSY	MK580525	Original	350.00
0562	RIGHT HEADLAMP ASSY	MK580526	Original	350.00
0677	L/F INDICATOR	MK581219	Original	188.00
0678	R/F INDICATOR	MK581220	Original	188.00
0717	L/POSITION LAMP	MK580529	Original	118.00
0718	R/POSITION LAMP	MK580530	Original	118.00
0826	R/F MUDFLAP	MC142140	Original	65.00
0828	R/F MUD FLAP BRKT	ML213529	Original	70.00
0830	R/F MUD PANEL	MK456198	Original	280.00
0887	L/F CORNER PANEL	MC976410	Original	320.00
0888	R/F CORNER PANEL	MC976411	Original	320.00
0900	FRONT PANEL CPL	ML230262	Original	680.00
0931	LOWER FRONT PANEL	MK707589	Original	450.00
1392	FRONT PANEL TRIM	MC976000	Original	290.00
1401	WINDSCREEN	MK403591	Original	880.00
1410	WINDSCREEN SEAL	MX943765	Original	250.00
1411	WINDSCREEN BOND KIT	Z2156507		0.00
1436	WASHER CONTAINER CPL	MK580578	Original	135.00
1450	WIPER MOTOR	MK581044	Original	450.00
1469	WIPER LINKAGE	MK580573	Original	420.00
1488	R/UPPER DOOR HINGE	MK997204	Original	85.00
1496	R/LOWER DOOR HINGE	MK997204	Original	85.00
1737	L/DOOR MIRROR ASSY	MK486111	Original	120.00
1739	L/DOOR MIRROR ARM	MK547646	Original	450.00
1741	L/DOOR MIRROR COVER	MK547012	Original	90.00
2205	L/F STEP	MK677506	Original	340.00
2206	R/F STEP	MK677507	Original	340.00
2803	BONNET CATCH	MK623030	Original	450.00
2810	CAB SUPPORT	MK622579	Original	1,250.00
2811	FRONT TORSION BAR	MK622762	Original	450.00
2813	L/CAB ATTACHMENT	MK622439	Original	250.00
2814	R/CAB ATTACHMENT	MK622440	Original	250.00
2819	L/R RUBBER MOUNTING	ML282432	Original	88.00
2820	R/R RUBBER MOUNTING	ML282432	Original	88.00
2825	L/F DAMPER BUFFER	MK622528	Original	155.00
2826	R/F DAMPER BUFFER	MK622528	Original	155.00
3404	R/F SIDE REFLECTOR	MK486520	Original	55.00
4242	R/F WHEELARCH PANEL	MK997121	Original	380.00
4327	L/BACKET CARRIER	MK620875	Original	180.00
4328	R/BACKET CARRIER	MK620873	Original	180.00
4329	L/IN INSTR PNL REINF	MK569098	Original	120.00
4330	R/IN INSTR PNL REINF	MK569090	Original	220.00
4331	INSTRUMENT PANEL	MK569703	Original	1,450.00
4445	HEATER BLOWER	ML298307	Original	1,590.00
7053	L/F LWR CONTROL ARM	MK527850	Original	380.00
7054	R/F LWR CONTROL ARM	MK527855	Original	380.00
7055	L/F UPP CONTROL ARM	ML326223	Original	350.00
7056	R/F UPP CONTROL ARM	ML326223	Original	350.00
7082	R/F STEERING KNUCKLE	MK527621	Original	550.00
7088	R/FR SHOCK ABSORBER	MK459972	Original	250.00
7131	L/F WHEEL HUB	MK527014	Original	480.00

BUC
MTG CRA

Code	Description	Part Number	Part Source	Price SGD
7132	R/F WHEEL HUB	MK527014	Original	sn 480.00 X
7300	STEERING GEAR	MK590224	Original	sn 1,850.00 X
7461	POWER STEERING PUMP	QC000052	Original CRA	sn 1,250.00 X
9645	HORN	MX916514	Original	sn 150.00 X
1004	AIR INTAKE TUBE ASSY	AIR INTAKE TUBE	Original	CM 850.00 ✓
f: OEM Parts				
n: Non-OEM Parts				
u: Used parts				
Savings				0.00
Subtotal				24,675.00
Total				24,675.00

Extras

Code	Description	Price SGD
1000	R/STEEL BODY TRUNK REAR STEEL BODY	400% 4,500.00*
	Total Extras	4,500.00

Final Calculation

	SGD	SGD
Parts	24,675.00	
Total Parts		24,675.00
Labour Time Base 10 WU/h		
Total 407.0 WU X 42.00 SGD/h	701.4 1,709.40	
Fixed Rate	330 1,550.00	1031.40
Total of Labour		3,259.40
Total Of Extras		4,500.00
Paint Work Time Base 10 WU/h		
Labour Cost 102.0 WU X 42.00 SGD/h	142.8 428.40	
Material Cost	77.68 127.99	220.48
Total Paint Including Material		556.39
Repair Cost Excludes GST		32,990.79
GST (+7.0%)		2,309.36
Repair Cost Included GST		35,300.15

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Ding Auto Pte Ltd

check items on 25/10/21

Parts Supplementary & Quotation Form

Attention: Mr. Kenneth Kong @ UKK	Works Order Number:
Vehicle Number: YP 3004 P	Our Reference Number:
Make & Model: Mitsubishi Fuso FEB 21	

S/NO	PART NUMBER	PARTS DESCRIPTION	QTY	UNIT PRICE	SURVEYOR REMARK	W/S REMARK
1		Engine Fan Cover	1	250.00	✓	
2		Cabin Stand	1	280.00	✓	
3		Propellor Bearing Mounting	1	380.00	✓	
4		Engine mounting RH	1	180.00	✓	
5		Engine mounting LH	1	180.00	✓	
6		Gear Box Mounting x 2 pcs	2	90.00	✓	
7		Engine Bracket RH	1	480.00	✓	
8		steering box bracket	1	190.00	✓	
9		speed meter sensor	1	320.00	✓	
10		Radiator expansion tank	1	195.00	✓	
11		Power steering oil tank	1	195.00	✓	
12		Door lock assy RH	1	280.00	✓	
13		Exhaust catalyst	1	2800.00	✓	
14		Rear speed sticker & pin	2	30.00	X	
15		Rear Axle box - Repair	1	300.00	X	

ESTIMATOR: Henry Lee

SURVEYOR: Kenneth @ UKK