



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0761/2021/ZK
DATE : 15-Sep-21
WIP : 44547

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/09/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days ok - Carrine 17/01/2022

OWNER'S NAME : MR ESCUDERO IAN HERMAN GONZALES
ADDRESS : 180 JOO CHIAT TERRACE
#03-05
SINGAPORE 427326
TELEPHONE : HP +65 98738049
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100321097-08
VEHICLE NO : SKH 2634 K
MODEL CODE : AUDI Q3 2.0 TFSI QU
MODEL YEAR : 22/11/2012
ENGINE NO : CCZ 290440
CHASSIS NO : WAUZZZ8U0DR030817
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Sep-21
PLACE OF ACCIDENT : UPPER EAST COAST ROAD AND
BEDOK SOUTH AVE 1 TURN

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKH 2634 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	S/N \$	280.00 \$	280.00
2	TO DISLodge AND REINSTAl REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	S/N \$	480.00 \$	480.00
3	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR LID.TO CUT OUT AND WELD REAR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT. REINSTALL ALL PARTS REMOVED	\$	4,400.00 \$	1,000.00
4	TO RESPRAY REAR BUMPER,REA LID REAR END PANELLING AND SPARE WHEEL HOUSING	\$	4,000.00 \$	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00 \$	192.00
TOTAL LABOUR CHARGES		:	\$ 9,352.00	\$ 3,602.00



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 2634 K

DAMAGED PARTS & PRICES						
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	REAR BUMPER	1	\$ 1,580.00	\$		1,264.00
2	REAR BUMPER FIXING SET	1	\$ 124.00			
3	REAR BUMPER SPOLIER	1	\$ 475.00	\$		380.00
4	REAR BUMPER CARRIER	1	\$ 651.00			
5	HEX BOLT	6	\$ 30.00			
6	REAR TAIL LIGHT FOAM PIECE - LH / RH LOWER	2	\$ 172.00			
7	REAR PARKING AID SENSOR	3	TBC			
8	REAR PARKING AID SENSOR SEAL	4	\$ 6.00			
9	REAR BUMPPER TAIL LIGHT - LH / RH	2	\$ 602.00	\$		240.40
10	REAR LID TAIL LIGHT - LH	1	\$ 1,335.00	\$		1,068.00
11	ADHESIVE	1	\$ 19.00	\$		14.88
12	AUDI EMBLEM	1	\$ 138.00	\$		110.00
13	Q3 EMBLEM	1	\$ 99.00	\$		79.04
14	2.0T EMBLEM	1	\$ 99.00	\$		79.04
15	QUATTRO EMBLEM	1	\$ 99.00	\$		79.04
16	REAR LID RUBBER	1	\$ 205.00			
17	REAR PANEL TRIM	1	\$ 572.00			
18	REAR PANEL	1	\$ 311.00			
19	REAR PANEL REINFORCEMENT	1	\$ 790.00			
20	REAR WHEEL ARCH COVER - LH / RH	2	\$ 516.00	\$		412.80
SUB TOTAL SPARE PARTS		:	\$ 7,823.00	\$	3,727.20	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKH 2634 K

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		
			b/f	S/NETT	REMARKS
21	REAR BUMPER WIRING SET	1	\$	515.00	
22	ARCRYLIC SEALANT	1	\$	180.00	
23	CRAVITY WAX	1	\$	140.00	
24	STONE CHIP	1	\$	180.00	
25	METAL FILLER POWDER	1	\$	280.00	
26	SUNDRIES	1	\$	300.00	
TOTAL SPARE PARTS		:	\$	9,418.00	\$ 3,727.20
TOTAL LABOUR CHARGES		:	\$	9,352.00	\$ 3,602.00
GRAND TOTAL		:	\$	18,770.00	\$ 7,329.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT