

⏪

⏩

1 of 2 ?

⏴

⏵

100% ▾

🖨

🔍 Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref: CS3/GRB21008552/Gv3-1		
64 CECIL STREET		Date: 21/09/2021		
#05-02 IOB BUILDING SINGAPORE 049711		Code: GRB		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLH 4457E	Veh. Inspected	SKW 6830E	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0003440	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	21/09/2021	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/08/2021	Inspection Date	21/09/2021	
Survey held at	Blk 7 Sin Ming SECTOR C, #01-82			
Repairer	CELEBRITY AUTO			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				