



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21009838/Etf3e2	
			Date: 02/11/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SM 72Z	
	Policy No.	Coverage (\$)	0.00	
	Claim No. M11D13722109	Excess (\$)	2,000.00	
	Assign From JOSEPHINE WONG	Assign Date	21/09/2021	
2. Vehicle Particulars & Condition				
	Make & Model B.M.W. 430i	c.c	1998	
	Engine No. HIDDEN	Year of Reg.	2017	
	Chassis No. WBA4V32060EA25540	Colour	WHITE	
	Odometer 85703 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/40 R18	GOODYEAR	5 mm
	L/H Front Tyre	255/40 R18	GOODYEAR	5 mm
	R/H Rear Tyre	255/40 R18	GOODYEAR	5 mm
	L/H Rear Tyre	255/40 R18	GOODYEAR	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 14/09/2021	Inspection Date	22/09/2021	
	Survey held at PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
	A)THE MARKET VALUE IS S\$170,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	