



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref:	CC6/TP21009846/Gpa3q2
Modern (Singapore) Access & Equipment Pte Ltd			Date:	24/02/2022
2 PENJURU LANE SINGAPORE 609183				
Attn: Klein Phua			Code:	TP2
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>				
	Insured Veh.	Veh. Inspected	YQ 2593G	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	21/09/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MITSUBISHI CANTER	c.c	2998
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	FEB21EA35018	Colour	WHITE
	Odometer	23870 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	195/85 R15	DUNLOP	6 mm
	L/H Front Tyre	195/85 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/85 R15	KENDA	6 mm
	L/H Rear Tyre	195/85 R15	KENDA	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.			
	REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	07/08/2021	Inspection Date	21/09/2021
	Survey held at	LKT GROUP PTE LTD 3006 UBI ROAD 1 #01-384 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	