



City Auto Pte Ltd (Co.Reg.No:199503435C)

160 Sin Ming Drive #05-01, Sin Ming AutoCity,
Singapore 575722

Tel: 6453 1235 Fax: 6453 7944 Email: jason@cityauto.com.sg

TP INSURER:

India International Insurance Pte Ltd (HQ)

Apt Blk 223D Compassvale Walk #08-677
Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	30/08/2021
Vehicle Reg. No.:	XE6616Z	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	Koh Chin Seng		
Make/Model:	MITSUBISHI FUSO, 10.7 D FV70HJA00064 (M)	Vehicle Reg. Date:	03/08/2021
Vehicle Colour:	White/Blue	Chassis No:	FV70HJA10104
Engine No:	470912C0621067		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day):	8		
Present Location:	CITY AUTO PTE LTD (HQ)		

*Not Authorised
Repairing
\$9275.44 3 days*

COST OF CLAIMS	Amount
Parts	55,398.98
Miscellaneous Items	11.00
Labour	820.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	56,229.98
+ GST 7.00% (S\$)	3,936.10
Nett Amount (S\$)	60,166.08

This claim is handled by: VRONICA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

reference

Source: (Last communicated: 21 Sep 2021)
 N/A MITSUBISHI FUSO 10.7 D FV70HJA00064 (M) (Model not available in database)
 Repairer's (Price communicated: Standard List)

Code: City Auto Pte Ltd/XE6616Z/21/09/2021 09:55
 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers
 with the END OF ESTIMATES marker on the last estimate page

Info: Items/values not in reference catalogue are prefixed with an asterisk *.

ates on Parts

Part No.	Particulars	%Disc	%Depr	Amount
	*DPD Assy	10.00	0.00	*51,849.49 FL
	*Mud guard RH front	10.00	0.00	*456.61 FL
	*Inforcement	10.00	0.00	*200.00 FL
	*Exhaust muffler heatshield - MX926260	10.00	0.00	*307.15 FL
	*Exhaust muffler heatshield - MX917050	10.00	0.00	*387.68 FL
	*Exhaust temperature sensor	10.00	0.00	*662.46 FL
	*Exhaust muffler NOX sensor - MX916501	10.00	0.00	*2,509.27 FL
	*Exhaust muffler NOX sensor - MX917068	10.00	0.00	*2,509.10 FL
	*ATS exhaust muffler harness	10.00	0.00	*2,672.66 FL

part. L=ListItemDisc.

Sub Total (\$\$)	61,554.42
- List Item Discount on L Items (\$\$)	6,155.44
Total Parts (\$\$)	55,398.98

City Auto Pte Ltd/XE6616Z/21/09/2021 09:55. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

nec 11.00 ✓

Sub Total (S\$) 11.00

Estimates on Labour

No Particulars

Labour Items

1 Labour to remove and realign side reinforcement
2 To replace DPF assy and reprogramme
3 To respray reinforcement

Lab.Type

Amount

New 250.00

New 450.00

New 120.00

Gross Labour Cost (S\$) 820.00

City Auto Pte Ltd/XE6616Z/21/09/2021 09:55. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: