

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	ale Des Experts En Au	utomok	Dile CS3/CTI21009852/Eu
	CHINA TAIPING IN	Re		CS/CT121009652/Euc	
	3 ANSON ROAD # SPRINGLEAF TOV	Da	ate:	21/09/2021	
			Co	ode:	СТІ
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMM 2275M	Veh. Inspected		PC 3031K
	Policy No.	DMPCSNW00076572100	Coverage (\$)		0.00
	Claim No.	SNM21D205244/C02/SMM2275 M/TOHHS	Excess (\$)		0.00
	Assign From	ALFRED TOH	Assign Date		21/09/2021
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
۱.	Description of Damages				
5. General Information					
	Accident Date	15/09/2021	Inspection Date		23/09/2021
	Survey held at	566 WOODLAND ROAD S728697			
	Repairer	CONNECT3			
āa.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				