



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2107403

64 CECIL STREET  
#05-02 IOB BUILDING  
SINGAPORE 049711

INV Date 27/10/2021  
Reference CS3/III21009855/Vtf3e2  
Code III2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SJV 9992T

Insured Veh. SLW 2548K

Claim No.

Policy No.

Accident Date 11/09/2021

Inspection Date 12/10/2021

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 12.10.2021 12.00pm	
- Dismantle Inspection 13.10.2021 01.14pm	
- After Repair Inspection 18.10.2021 11.32am	
Merimen Fee	11.00
<b>Subtotal</b>	<b>131.00</b>
<b>GST (7%)</b>	<b>9.17</b>
<b>Grand Total</b>	<b>140.17</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**KHM**