




Service Requests

Messages

Claims



Service Request Details

Claim	S1M03IDV
Reference	CS3/ASM21009863/Etce2 
Loss Date	18 September 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Contract Type	VA1
Contract Name	VA1

Actions

Next Step Wait for: Approve invoice

[Add Invoice](#)

Vehicle Information

Incident SDT2682R
Vehicle
Registration #

Make TPVD BMW

Model 530I

Vessel/Truck/Flight

Vessel

Quote

Insured

WRYTE MARINE ENGINEERING PTE
LTD 190 MIDDLE ROAD, #19-05

Type of
Loss

Third Party Vehicle
Damage

FORTUNE CENTRE, 188979,
Singapore 94885556
WELLFIELD.INS@GMAIL.COM

Truck

Flight

Report Date 20 Sep 2021 10:43:58 PM

Request 21 21
Date September September
2021 2021 4:18 PM

Due Date

Services Pre-Repair Survey

Service Address

, , ,

Primary Contact

Primary Contact/Insured

WRYTE
MARINE ENGINEERING PTE LTD 190
MIDDLE ROAD, #19-05 FORTUNE
CENTRE, 188979, Singapore 94885556
WELLFIELD.INS@GMAIL.COM

Claim Handler

TEO Kitty
kitty.teo@axa.com.sg

Additional Instructions [\(expand\)](#)




[Messages2](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)







Document Type






Document SubType


[+ Upload Documents](#)

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2106654.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	27 September 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	27 September 2021
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 September 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 September 2021
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	27 September 2021
 RESURVEY.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 September 2021
 LKKPhotosIn6.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	23 September 2021
 AXA Immediate Advice _ TP -SDT 2682R.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	23 September 2021
 EMAIL TP REG.msg.msg	Letters and Correspondence	Solicitor / Advocate	VISHNU BATHAM Shekhar	

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
				21 September 2021
 GIA INSD SMX5361U.pdf.pdf	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	21 September 2021
 EMAIL TP REG.pdf.pdf	Letters and Correspondence	Solicitor / Advocate	VISHNU BATHAM Shekhar	21 September 2021
 OI VIDEO.mp4	Evidence	Videos	TEO Kitty	21 September 2021
 SDT2682R TP GIA.pdf.pdf	Reports & Statement	GIA Report	TEO Kitty	21 September 2021
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	21 September 2021

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 SMX5361U INSD GIA.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Size 2	20 September 2021

«

1

»