



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM21009874/Epa3q2 Date: 01/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 5168S	Veh. Inspected	FBE 1147D
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03GDZ	Excess (\$)	0.00
	Assign From		Assign Date	21/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA T135	c.c	135
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	5YP301321	Colour	BLACK
	Odometer	31340 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	70/90-17	DIABLO	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	80/90-17	DIABLO	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/08/2021	Inspection Date	21/09/2021
	Survey held at	CREATION MOTORS 649B JURONG WEST STREET 61, #16-296, SINGAPORE 642649		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	