

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadul Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 11 Oct 2021

Dear Sirs :

Fax : 6224 1047

**RE : ESTIMATE COST FOR MERCEDES BENZ CITAN - GBK1061K
ACCIDENT INVOLVING GBK1061K & SMP4500J ON 17/09/2021**

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
<u>Labour Charge & Misc</u>			
	To remove, repair, replace & install damaged parts.	} }	\$ 500.00 ³⁰⁰
	To putty & spray painting		\$ 600.00 ⁴⁵⁰
Total			\$ 1,100.00

Taufik 97415749
wp 11/10/21 @ 3:50pm
p/p Resurvey after repair
taufik@lkkauto.com
3 days

\$ 750 #
3 days
#

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: