



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/771/2021/JT
DATE : 20-Sep-21
WIP : 45132

\$3318

Xiao Chen

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/9/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR THAM WAI LEONG
ADDRESS : 317 TELOK KURAU ROAD
SINGAPORE 423865
TELEPHONE : HP +65 98318781
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800079954-03
VEHICLE NO : SMC 5466 L
MODEL CODE : A6 1.8 TFSI S
MODEL YEAR : 7/7/2018
ENGINE NO : CYG 023417
CHASSIS NO : WAUZZZ4GXJN039737
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Sep-21
PLACE OF ACCIDENT : TRAFFIC JUNCTION BETWEEN
FRANKEL AVENUE AND CHANGI ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SMC 5466 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CEHCK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER BOTH HEADHLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	500 ✓
4	TO REPSRAY FRONT BUMPER AND FRONT BUMPER LOWER SPOILER. 550 300	\$ 1,600.00	850 ✓
5	TO CARRY OUT CALIBRATION SETTING FOR FRONT RADAR SENSOR AND DISTANCE REGULATION	S/N \$ 480.00	? ✓
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,752.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 5466 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	1	\$ 3,268.00	<i>x</i>
2	FRONT BUMPER FIXING PARTS	1	\$ 543.00	<i>x</i>
3	FRONT BUMPER GRILLE - LOWER CENTER	1	\$ 128.00	<i>x</i>
4	FRONT BUMPER LOCKING CLIP	14	\$ 55.00	<i>x</i>
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 219.00	<i>x</i>
6	FRONT BUMPER SPOILER <i>2nd</i>	1	\$ 945.00	<i>756</i>
7	RADIATOR GRILLE <i>3rd</i>	1	\$ 1,934.00	<i>x</i>
8	RADIATOR GRILLE COVER	1	\$ 36.00	<i>x</i>
9	RADIATOR GRILLE PARKING AID SUPPORT - LH / RH	2	\$ 132.00	<i>x</i>
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,144.00	<i>x</i>
11	FRONT BUMPER LOWER COVER - LH / RH	2	\$ 102.00	<i>x</i>
12	FOAM FILLER PIECE	1	\$ 237.00	<i>x</i>
13	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 872.00	<i>x</i>
14	FRONT BUMPER TOP COVER	1	\$ 123.00	<i>x</i>
15	"CAUTION" STICKER	1	\$ 14.00	<i>x</i>
16	FRONT BUMPER PARKING AID	2	TBC	<i>x</i>
17	FRONT WHEEL SPOILER - LH / RH	2	\$ 528.00	<i>x</i>
18	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	<i>x</i>
19	LED HEADLIGHT - LH / RH	2	\$ 19,080.00	<i>x</i>
20	HEADLIGHT HOSE	1	\$ 478.00	<i>x</i>
SUB TOTAL SPARE PARTS		:	\$ 30,074.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMC 5466 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN - RH	1	\$ 47.00	X
22	HORN BRACKET - RH	1	\$ 29.00	X
23	RADIATOR AIR GUIDE - LH / RH	2	\$ 58.00	X
24	RADIATOR AIR GUIDE - CENTER	1	\$ 29.00	X
25	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ ✓
26	SUNDRIES <i>Not Rec</i>	1	\$ 300.00	? X
TOTAL SPARE PARTS		:	\$ 30,597.00	
TOTAL LABOUR CHARGES		:	\$ 4,752.00	
GRAND TOTAL		:	\$ 35,349.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
 SURVEYED DATE : *22/09/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *not Authorised, 03 Days.*

[Signature]

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT