



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20210917/0336		LOCATION OF FIRE: Along Telok Blangah Road Near lamp post no. 78 Singapore	
FIRE REPORTED ON : 17 September 2021			
TIME OF CALL : 09:52:27 hrs			
STATION COVERAGE : Sentosa Fire Station			
2. INCIDENT INFORMATION			
FIRE INVOLVED: The contents of a carriage deck of an Nissan lorry (YL8552L) at the above said location.			
METHOD OF EXTINGUISHMENT: By SCDF crew using two compressed air foam backpacks and an hose reel jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental			
DAMAGE SUSTAINED: As a result of the fire, the contents of carriage deck comprising carton boxes of air condensing unit(s), air conditioning fan coil unit(s) and other miscellaneous items were damaged. The exterior and interior cabin of the lorry sustained heat and smoke damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
 ANG LI FENG for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.