

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jonathan Lim
CLAIM DEPARTMENT
DID : 66547606
FAX : 66547540

Date : 24/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>Nett Item</u>			
1	FRONT BUMPER	571.90	
1	FRONT RH BUMPER RETAINER	181.90	
10	FRONT BUMPER CLIP	50.00	
1	FRONT RH SIDE STEP	67.50	
1	FRONT RH MUDFLAP	105.50	
1	RH "A" PILLAR	RESTORE	
1	FRONT DOOR RH	1,071.40	
1	FRONT RH FENDER	RESTORE	
1	FRONT RH UPPER ARM	377.90	

Date : 24/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT RH LOWER ARM	228.40	
1	FRONT RH ABSORBER	140.20	
2	FRONT RH ABSORBER RUBBER STOPPER	40.00	
1	FRONT RH ABSORBER BRACKET		
1	FRONT RH KUNCKLE ARM	315.20	
1	FRONT RH WHEEL HUB	453.00	
1	FRONT RH WHEEL BEARING	231.00	
1	TIE ROD END RH	142.00	
1	TIE ROD RH	98.00	
1	FRONT RH ABS SENSOR	397.00	

Date : 24/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT RH BRAKE CALIPER HOSE	67.90	
1	WHEEL RIM COVER	161.50	
1	FRONT RH TYRE RIM15 INCH	237.50	
	Sub Total	4937.80	
	Discount 10% On Parts	(493.78)	
	Special Nett Item		
1	COMPANY DECAL STICKER	20.00	
1	TYRE 195R15C	200.00	
1	TOWING CHARGES FROM ACCIDENT AREA INTO W/SHOP	150.00	

Date : 24/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	370.00	
	<u>Labour & Misc</u>		
	LABOUR TO FACILITATE REPAIR	800.00	
	TO REMOVE & INSTALL RHF UNDERCARRIAGE PARTS	200.00	
	TO REMOVE & INSTALL RHF RIM INCLUDING TYRE BALANCING	20.00	
	MOUNT VEHICLE ON CHASSIS ALIGNMENT BENCH & RECTIFY CHASSIS TO RECOMMENDED SPECIFICATION	1,800.00	
	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	80.00	
	TO RESET & RE-PROGRAM WARNING LIGHT ON	120.00	

Date : 24/09/2021

To : LKK AUTO CONSULTANTS PTE LTD

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTHCVE000057

Accident Date : 11/09/2021

Vehicle No : GBG-2465-T

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO APPLY ANTI RUST COATING	80.00	
	TO SPRAY PAINTING ON AFFECTED AREAS	800.00	
	Sub Total	3900.00	

8,714.02

Remarks:

SUB TOTAL

GST 7.0 % 609.98

TOTAL 9,324.00

Surveyor's name: _____

Principal's name: ETHOZ Group Ltd

Survey Date & Time: _____