

ASS. REC. BY:

Tang Jih

REF:

ALG.

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

\$79K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL569316

Yr Regn:

2017 Sep

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

c.c

999

Colour

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

76785

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAY ZEE8V5 J/03790

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

24/7/21 0230pm

Survey held at

Premium Auto Lib

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L&M (F)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0781/2021/KS
DATE : 22-Sep-21
WIP : 45597

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HARI JAYA SINGH KIRAN KUMAR
ADDRESS : 9 RIVERVALE CRESCENT
#06-22
SINGAPORE 545086
TELEPHONE : HP +65 92392646
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700058585-03
VEHICLE NO : **SLS 6931 G**
MODEL CODE : A3 1.0 SEDAN 8V
MODEL YEAR : 30/9/2017
ENGINE NO : CHZ 531220
CHASSIS NO : WAUZZZ8V5J1013790
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Sep-21
PLACE OF ACCIDENT : 31 GRANGE RD, SG 239702

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLS 6931 G

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	✓
2	TO DISMANTLE AND RENEW LHS REAR DOOR. TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.	\$	2,100.00	100
3	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER AND LHS SILL PANEL. ✓	\$	3,000.00	1650
4	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✓
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		: \$	5,922.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SLS 6931 G

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH	1	\$ 3,039.00	bt ✓
2	REAR DOOR OUTER SEAL - LH	1	\$ 161.00	rel ✓
3	BONDING AGENT	1	\$ 49.00	?
4	CLEANING SOLUTION	1	\$ 68.00	?
5	APPLICATOR	1	\$ 8.00	?
6	REAR DOOR ATTACHMENT PARTS - LH	1	\$ 129.00	X
7	REAR DOOR CATCH	1	\$ 94.00	?
8	REAR WHEEL SPOILER - LH REAR	1	\$ 65.00	?
9	REAR WHEEL HOUSING LINER - LH	1	\$ 240.00	?
10	REAR WHEEL HOUSING LINER ATTACHMENT PART- LH	1	\$ 89.00	?
11	REAR ALUMINIUM RIM - LH	1	\$ 1,166.00	cut ✓
12	STONE CHIP	1	\$ 180.00	rel ✓
13	REAR TYRE - LH	1	\$ 250.00	X
14	SUNDRIES		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 5,838.00	
TOTAL LABOUR CHARGES		:	\$ 5,922.00	
GRAND TOTAL		:	\$ 11,760.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
24/9/21 @ 1430
Not Authorise Ex! to be advise
Resurvey before paint
05 days
tanpin@thkauto.com.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT