



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21008402/Guf3e2-1	
			Date: 11/10/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1335M	Veh. Inspected	SJG 7704B
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/08/21/1004	Excess (\$)	0.00
	Assign From	KAREN CHAN	Assign Date	20/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	mitsubishi LANCER 1.6	c.c	1584
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	JMYSTCS3A8U007586	Colour	BLUE
	Odometer	110367 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	6 mm
	L/H Front Tyre	195/65 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/08/2021	Inspection Date	11/08/2021
	Survey held at	CARSMITH PTE LTD BARTLEY BIZ CENTRE, 13 KAKI BUKIT ROAD 4 #01-20 SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	