



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0782/2021/KS
DATE : 27-Jul-21
WIP : 45649

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS BOYD LARA MEREDITH
ADDRESS : 93 ROBERTSON QUAY
SINGAPORE 238255
TELEPHONE : HP +65 82990347
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800136280-02
VEHICLE NO : **SMF 7304 S**
MODEL CODE : AUDI Q2 1.4 TFSI MU
MODEL YEAR : 22/11/2018
ENGINE NO : CZE 844710
CHASSIS NO : WAUZZZGA0KA010814
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Sep-21
PLACE OF ACCIDENT : 56 BAYSHORE RD, SG 469980



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMF 7304 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE ,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING ATD.	S/N \$	480.00 X	
2	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00 ✓	
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS SILL PANEL AND DOOR ENTRANCE. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	4,000.00 1000	
4	TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS SILL PANEL, LHS WING MIRROR COVER AND DOOR ENTRANCE.	\$	4,000.00 1100.	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	
TOTAL LABOUR CHARGES		:	\$	9,072.00



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMF 7304 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT FENDER - LH	1	\$ 1,147.00	X
2	FRONT FENDER ATTACHMENT PARTS	1	\$ 40.00	X
3	FRONT FENDER BRACKET - LH	1	\$ 16.00	X
4	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 644.00	X
5	FRONT DOOR - LH	1	\$ 2,756.00	bt ✓
6	FRONT DOOR ATTACHMENT PARTS - LH	1	\$ 94.00	?
7	FRONT DOOR CATCH - LH	1	\$ 120.00	?
8	FRONT DOOR INNER SEAL - LH	1	\$ 161.00	newer?
9	FRONT WING MIRROR MOUNTING - LH	1	\$ 1,024.00	X
10	FRONT DOOR COVER - LH	1	\$ 257.00	de ✓
11	FRONT POWER WINDOW REGULATOR - LH	1	\$ 282.00	?
12	FRONT POWER WINDOW REGULATOR MOTOR - LH	1	\$ 241.00	?
13	FRONT DOOR INNER COVER - LH	1	\$ 13.00	?
14	SIDE MEMBER TRIM - LH	1	\$ 238.00	ant ✓
15	FRONT DOOR SEAL OUTER - LH	1	\$ 50.00	new ✓
16	STONE CHIP	S/N	\$ 180.00	?
17	SUNDRIES	1	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 7,563.00	
TOTAL LABOUR CHARGES		:	\$ 9,072.00	
GRAND TOTAL		:	\$ 16,635.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tan Kah 97495749
24/4/2025
Not Authorise Ex to be advise
25 days
Resurvey before paint
Tan Kah @ Khantam

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT